

UNIVERSITY OF DELAWARE
NEWARK, DELAWARE
19711

CORRESPONDENT'S PHONE: 301-736-1442

SCHOOL OF ENGINEERING
DEPARTMENT OF CIVIL ENGINEERING
5132 DUPONT MALL
PHONE: 301-736-1442

January 9, 1970

Mr. Uldis Karins
Assistant County Engineer
N. C. County Engineering Building
P. O. Box 165
Wilmington, Delaware 19899

Dear Mr. Karins:


Enclosed please find the two copies of water quality data in connection with the investigations at the Tybouts Corner Sanitary Landfill up to November 28, 1969.

In addition to the well's 1, 4, 5, 6, and 12 which were destroyed, now the well 13 also has been covered over with dirt and is inaccessible. That means, we have only seven out of thirteen wells remaining to investigate the water quality changes in the landfill area. This loss of water quality measurement capability will hamper our proper evaluation of the water quality changes in the landfill area. New well points should be put in soon in order to alleviate this situation.

We have already written to you about the coliform count problem in one of the houses (Wolfe residence) adjoining the landfill. We are investigating the problem further and hope the State Board of Health will also independently investigate it.

We will send you the graphical picture of the water quality changes in the well in the landfill from July 1969 to December 1969 next time and also interpret the collected six monthly data.

Sincerely yours,



Shankha K. Banerji

SKB/mht

Enclosures

027883

Rec'd
1/12/70

000211